

May 7, 2008
61032-DRO-559296-08

Steven E. Bushey
Simmonds Precision Products
100 Panton Road
Vergennes, VT 05491

Attention: Steven E. Bushey

Subject: Boeing Support of Supplier's Request for Boeing/FAA Designee Authorization

Reference: Supplier Request Letter dated May 5, 2008



The Boeing Designee Management office is requesting that you process the following personnel for approval to perform work on Boeing programs and projects:

<u>Name</u>	<u>FAA Designee #</u>	<u>Function Codes</u>
Simmonds Precision Products	ODARF800757NE	08(parts only) 19, 20, 21

Please forward a request for authority to your local FAA Manufacturing Inspection District Office (MIDO). This letter supporting your request must be included with your request for authority.

The FAA request for authority should encompass the certification level required to satisfy the elements of FAR 183.31, Parts (a) (1) parts only (2), (b)(1)(2) and (c), or FAR 183.33, as applicable, and Order 8100.8.

The COA should list the designation certificate number, fixed base of operation, and date of designation and expiration. The authorized functions/limitations must identify "The Boeing Company, 7755 East Marginal Way South, Seattle, Washington, 98108-4026" as a PAH (Production Approval Holder).

When you have received notification of approval of authorization, submit a copy of the FAA Certificate of Authority (COA) Notification of Appointment Letter, identifying "The Boeing Company, 7755 East Marginal Way South, Seattle, Washington, 98108-4026" as a PAH (Production Approval Holder), and the ODAR authorized function codes and limitations, to: The Boeing Company, Designee Management Office, Internal Mail Stop OY-CK, P.O. Box 3707, Seattle, WA 98124-2207.

If you require additional information or assistance, please contact the undersigned or Kellie Fryman at 425-266-7966

Concurrence by:

A handwritten signature in black ink, appearing to read "Donald P. Townsend".

Donald P. Townsend
Designee Management
Regulatory Administration
The Boeing Company

A handwritten signature in black ink, appearing to read "Tim Vranna".

For Tim Vranna
Transport Airplane Directorate
Aircraft Certification Service
Manager, Certification
Management Office - Boeing

May 6, 2008
ODAR 6762008

To: Boeing DRO Management Office

Mail Code: O8-95

Attention: Kellie Fryman

Subject: SM FAA Regulatory & Industry Affairs Justification/Recommendation
of Supplier's Request for FAA Designee Authorization

Reference: Attached letter dated May 5, 2008

The Boeing Supplier Management Regulatory Affairs organization has received and reviewed the referenced Supplier Request for FAA Designee Authorization. It has been determined that the supplier has a need for an FAA designee.

This letter is the Supplier Management SQ Regulatory Affairs authorization and request to process the following personnel for approval to perform work on Boeing programs and projects:

<u>Name</u>	<u>FAA Designee #</u>	<u>Function Codes</u>
Simmonds Precision Products (d/b/a Goodrich SIS-VT)	ODARF-800757-NE	08 (parts only), 19, 20 & 21.

100 Panton Road
Vergennes, VT 05491
Supplier Code 051762

Attached you will find a copy of the supplier request letter and other applicable information required to process this renewal request.

If you require additional information or assistance, please contact the undersigned or Darlene Holloway at (425) 266-6542.



Guy Goldsworthy
ODAR Administration
BCA Supplier Management & Supplier Quality
The Boeing Company
08-46, (425) 266-6541



Sensors and Integrated Systems - VT
100 Panton Rd
Vergennes, VT 05491
Tel: 802-877-2911
Fax: 802-877-4911

An ISO 9001 Registered Company

May 5, 2008

The Boeing Company
Boeing Commercial Airplane Group
Global Partners PQA
P.O. Box 3707
Seattle, WA 98124

Attention: Guy Goldsworthy
ODAR/Delegation Administration - PQA

Subject: Boeing FAA ODAR Authorization

Reference: a) FAA Order 8100.8A Section 301

Dear Guy,

I would like to request that Simmonds Precision Products, Inc., d/b/a/ Goodrich Sensors and Integrated Systems, (SIS-VT) Certificate number ODARF-800757-NE, be considered for continuation to perform work on Boeing programs and projects as an ODAR on behalf of a PAH (Production Approval Holder). The ODAR authorization requested is required for the execution of Export Airworthiness tags on Class II and III products. This request is also being made to help support new Boeing programs requiring certification, conformity inspections for the 787 Dreamliner.

Goodrich SIS-VT has been an ODAR approved facility for the past twelve years and maintains three Authorized Representatives under the ODAR authorization.

- 1) Boeing programs presently under production and certification, all Boeing commercial airframes 737, 747, 767, 777 all models (primary system is fuels) and present certification program is 787, approximately 300 FAA Requests for Conformity are still active.
- 2) Our fixed base of operations is located at 100 Panton Road Vergennes, VT 05491.
- 3) Our present certification number ODARF-800757-NE designation expires July 31, 2008 (copy attached).
- 4) Our function codes are 08, 19, 20 & 21.

If there are any questions and/or we can be of any further assistance please do not hesitate to contact us. Thanks you for consideration in this matter.

Sincerely,

A handwritten signature in dark ink, appearing to read "Steven E. Bushey".

Steven E. Bushey
Quality Assurance Engineer
FAA ODAR Coordinator
Repair Station Chief Inspector
802/877-4814 FAX: 802/877-4160
Email: steve.bushey@goodrich.com

051762